



Coping stone granite Cutting, Nosing and Fixing work.







Pool View after Coping stone Fixing Work

Jacuzzi Sitting Stage Construction work



View of Jacuzzi Sitting Stage – Part of Pool



CONSTRUCTION OF ROOF TOP SWIMMING POOL Construction of Water falls Wall





CONSTRUCTION OF ROOF TOP SWIMMING POOL JACUZZI PLUMBING WORK









CONSTRUCTION OF ROOF TOP SWIMMING POOL POOL PLUMBING WORK







CONSTRUCTION OF ROOF TOP SWIMMING POOL Filtration Room Plumbing Work & Electrical Work





CONSTRUCTION OF ROOF TOP SWIMMING POOL Anti-skid Decking Tile Fixing Work



Waterfalls Crystal Glass Mosaic Tiles Fixing & Epoxy Grouting work.



CONSTRUCTION OF ROOF TOP SWIMMING POOL Glass Mosaic Tile Marking & Fixing Work





CONSTRUCTION OF ROOF TOP SWIMMING POOL Glass Mosaic Tile gap Filling using Epoxy Grouting work





CONSTRUCTION OF ROOF TOP SWIMMING POOL Mural Design Tiles Fixing Work





CONSTRUCTION OF ROOF TOP SWIMMING POOL SS Safety Railings Fixing work around the decking area & Steps.



CONSTRUCTION OF ROOF TOP SWIMMING POOL Underwater Pool LED Light Fixing Work



Final View of Water falls in the Pool



CONSTRUCTION OF ROOF TOP SWIMMING POOL Beautiful View of Swimming Pool With Waterfalls & Jacuzzi



Beautiful Day View of Water filled Swimming Pool With Waterfalls & Jacuzzi



Beautiful Night View of Swimming Pool With Waterfalls & Jacuzzi





PREEMIYAR POOLS PVT LTD best pool for better swimming ...

For more information, please contact:

BENGALURU H.O.	MYSORE	HASSAN/COORG/CHIKMAGALUR
Preemiyar Pools Pvt Ltd,	Preemiyar Pools Pvt Ltd,	Preemiyar Pools Pvt Ltd,
# 593, Nesara, 2 nd Floor,	# 495, Mathrushree,	Shrungari Nilaya,
2 nd Main, Opp H.M.V School,	'G' Block,	Near MKS Lions School,
Annapoorneshwarinagar,	Ramakrishnanagar,	Fort, Konanur - 573 130,
Bengaluru - 560 091, India	Mysore - 570 006, India	Hassan Dist, India
Ph: +91- 94484 - 56552	Ph: +91- 636463 - 1155	Ph: +91-94484-60658

www.preemiyarpools.com preemiyarpools@gmail.com

